



<div><div>Bone Conduction Headphones</div><div>User Manual</div><div></div><div><div>Operating instructions and Warranty description</div></div></div>	<div><div>Schematic and Accessories</div><div></div><div><div>① TPYE-C charging port</div><div>④Microphone</div><div>② Indicator/Microphone</div><div>⑤ *+ key</div><div>③ "MFB" key</div><div>⑥ *- key</div></div><div><div>Packing List</div><div>1.Bone Conduction Bluetooth Headphones</div><div>2.TYPE-C charging cable</div><div>3.User manual</div></div></div>	<div><div>Instructions for use</div><div><div>Power On</div><div>Press and hold the "MFB" for about 3 seconds,when the indicator light flashes alternately red and blue,it means the headset is turned on.</div></div><div><div>Bluetooth connection</div><div>For the first use,after the headset is turned on normally ,it will enter the Bluetooth pairing state.At this time, you can search for "K50Pro" in the Bluetooth settings of the mobile phone. After clicking the connection is succesful, the indicator light will turn off, and the blue light will flash once every 5 seconds when playing music.</div></div><div><div>Change paired device and connect back</div><div>Disconnect the current paired device Bluetooth, the headset indicator light flashes alternately red and blue, other devices can search for "K50Pro", click to connect "K50Pro". The bone conduction headset supports automatic reconnection to paired devices. After normal power on, it will automatically reconnect to the last connected device. Please ensure that the front end (such as mobile phone Bluetooth) is normally turned on.</div></div><div><div>Power Off</div><div>Press and hold the "MFB" button for about 3 seconds to turn off the power. The indicator light will turn off.</div></div></div>	<div><div>Charge</div><div>When connected normally,the phone will display the power of the headset. When the power is low, plug in the charging cable to charge it.</div><div><div>Note: 5V charging devices such as mobile phone chargers can charge the headset.</div></div><div><div>Instructions</div><div><div>General state</div><div>press the "MFB" for 3 second----Power On/Off</div><div>press the "MFB" for 1 second----activate voice assistant</div></div><div><div>Play status</div><div>click the "MFB"----- play/pause</div><div>Long press "--" ----- previous song</div><div>Long press "+" ----- next song</div><div>click " + " ----- volume up</div><div>click " - " ----- volume down</div></div><div><div>Call status</div><div>click the "MFB"----- answer the phone</div><div>click the "MFB"----- hang up the phone</div><div>Long press the "MFB"----- reject the call</div></div></div></div>	<div><div>Indicator light description</div><div>Alternating red and blue: pairing status</div><div>Light off: connected and waiting to play</div><div>Steady red light: charging</div><div>Steady blue light: fully charged</div><div><div>Product parameters</div><div>* Model: K50Pro</div><div>* Bluetooth version: 5.3</div><div>* Weight: 28g</div><div>* Battery: 230mAh</div><div>* Charging time: about 2 hours</div><div>* Playing time: 8-12H&70% volume</div><div>* Talk: -38dB</div><div>* Waterproof: IPX6</div><div>* Bluetooth connection distance: 10 m</div><div>* Input: 5V/500mA</div><div>* Protocol: A2DP, AVRCP, HSP, HFP</div></div></div>	<div><div>Troubleshooting</div><div><div>Can not boot</div><div>Determine whether the headset is fully charged and whet her the key is misoperated, and charge it to activate t he headset.</div></div><div><div>No Bluetooth connection</div><div>Whether the headphone indicator blinks alternately red and blue</div></div><div><div>Unable to automatically reconnect</div><div>Determine whether the front end (such as mobile phone Bluetooth) is enabled properly.</div></div><div><div>Low volume of headphones</div><div>Whether the volume of the phone is increased,and whether the wearing mode is correct</div></div></div>
---	--	---	---	---	--